

EMSL Analytical, Inc.

200 Route 130 North, Cinnaminson, NJ 08077 (800) 220-3675 / (856) 786-0327 Phone/Fax:

http://www.EMSL.com cinnaminsonradonlab@emsl.com

EMSL Order: CustomerID:

ProjectID:

381602726

PGCS62

CustomerPO:

Karen Bowlding **Prince George's County School** 13300 Old Marlboro Pike Upper Marlboro, MD 20772

Phone: (301) 952-6559 Fax: (301) 952-0346 Received: 03/24/16 10:50 AM

Analysis Date: 3/25/2016 Collected: 3/18/2016

Project: Carmody Hills

Carmody Hills Test Site:

Capitol Heights, MD 20743

Test Report: Radon in Air Test Results

Samples for EMSL Kit 142174

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Te Stop	emperature F	Humidity %	Sample Type
239661	Teacher's Lounge	0.8	3/18/2016	3/22/2016	70	50	Customer
381602726-0001			11:56:00 AM	9:45:00 AM			
Sample Notes:							
Cample Notes.							
Samples for EMSL Kit 1	42163	Radon Activity		Τε	emperature	Humidity	
•	42163 Location	Radon Activity pCi/L	Start	Te Stop	emperature F	Humidity %	Sample Type
Samples for EMSL Kit 1		,	Start 3/18/2016			,	Sample Type Customer

The radon test was performed using a liquid scintillation radon detector/s and counted on a liquid scintillation counter using approved EPA testing protocols for Radon in Air testing. The EPA recommends fixing your home if the average of two short-term tests taken in the lowest lived-in level of the home show radon levels that are equal to or greater than 4.0pCi/L. The EPA recommends retesting your home every two years.

Please contact EMSL Analytical, Inc. or your State Health Department for further information.

All procedures used for generating this report are in complete accordance with the current EPA protocols for the analysis of Radon in Air.

Report Note

Sample Notes:

Analyst(s)	Y amac France Ruse
Tiffanie Cosgrove (2)	Laura Freeman, Interim Laboratory Manager &
	Subash Rashat, New Jersey Radiation Specialist NJ MES 10152
	or other approved signatory

In no event shall EMSL be liable for indirect, special, consequential, or incidental damages, including, but not limited to, damages for loss of profit or goodwill regardless of the negligence (either sole or concurrent) of EMSL and whether EMSL has been informed of the possibility of such damages, arising out of or in connection with EMSL's services thereunder or the delivery, use, reliance upon or interpretation of test results by client or any third party. We accept no legal responsibility for the purposes for which the client uses the test results. In no event shall EMSL be liable to a client or any third party, whether based upon theories of tort, contract or any other legal or equitable theory, in excess of the amount paid to EMSL by client thereunder. The test results meets all NELAC requirements unless Accreditations: NRSB ARL6006, NJ DEP 03036, MEB 92525, PÁ 2573, IN 00455, IA L00032, RI RAS-024, ME 20200C, NE RMB-1083, NY ELAP 10872, NM 885-10L, FL RB2034, OH RL-39, NRPP #106178AL, KS-LB-0005

Samples analyzed by EMSL Analytical, Inc. Cinnaminson, NJ Accreditations: NRSB ARL6006, NJ DEP 03036, MEB 92525, PA 2573, IN 00455, IA L00032, RI RAS-024, ME 20200C, NE ŘMB-1083, NY ELAP 10872, NM 885-10L, FL RB2034, OH RL-39, NRPP #106178AL, KS-LB-0005. Subash Rashat certification #MES10152

Initial report from 04/01/2016 07:30:51

Please visit www.radontestinglab.com